


Left T-wing



LOG # LW-36

TARGET # _____

Pilot


Coord Lat: _____

See Additional Comments

LONG: _____

Debris Field. No TAC attached!!

L/H wing Inb'd Aileron section measures
3' long x 4' wide. Section has inb'd actuator
ATTACHED. Aileron displays signs of
BURNING lower section "Honey comb" panel
Also has BURN ON upper half section



Bottom ↑
Fwd

View
TMCB 10/13/96 - TWA
R. [Signature] - BOEING

A. J.
LICURAS
FPA

S. GREEN - ALPA
11-6-96
D. [Signature] - IAM
11-7-96
- NTSB

Stephanie Klyman US
FBI 10-28-96

LW-36 Additions / Comments

Pg 2 of 2

1. Inboard rib web unbowed.
2. Outboard rib web is partially burned through.
3. Upper metal strip partially burned through.


SD GREEN 11-16-96


ALPA


 Peter A. Scott

12-6-96

 Tim McKinney
TWA 12-6-96

 Dennis Santiago IAM
12-6-96

 Tom Todino
FANA 12-6-96

 S. Roth
BOEING 6 DEC 96